
























A1 = Top Left of ADC connector





Need to add ZCU216 board anchors mounting holes

H50 = Bottom Right of ADC connector



ADC connector is on right side

A1 = Top Left of DAC connector



H50 = Bottom Right of DAC connector


Need to add ZCU216 board anchors mounting holes

DAC connector is on left side



Fermilab		Operated by Fermi Research Alliance, LLC under Contract No. DE-AC02-07CH11359 with the United States Department of Energy	
Size	Rev	Board2Board_DAC	ENGINEER: Cancello, Treprow DRAWN: N. Wilcox
C	A		
Number	Date: 5/29/2024 Time: 4:21:46 PM	Sheet 6 of 9	CHECKED: APPROVED:

C:\Users\mfr21\OneDrive\Documents\Board2Board_DAC_RevD.docx



MS21 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS22 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS23 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS24 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349
TSP1 91075A460	TSP2 91075A460	TSP3 91075A460	TSP4 91075A460
CN1 99022A101	CN2 99022A101	CN3 99022A101	CN4 99022A101
MS25 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS26 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS27 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS28 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349
TSP5 91075A460	TSP6 91075A460	TSP7 91075A460	TSP8 91075A460
CN5 99022A101	CN6 99022A101	CN7 99022A101	CN8 99022A101
MS29 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS30 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS31 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349	MS32 Cannot open file C:\Altium\RF_ Gen3\Mechanic alScrew.PNG. File does not 91772A349
TSP17 91075A460	TSP18 91075A460	TSP19 91075A460	TSP20 91075A460
CN17 99022A101	CN18 99022A101	CN19 99022A101	CN20 99022A101

